

Community Living Arrangement Inspection Report Summary

Beech Mountain Road

97 Beech Mountain Road Mansfield, CT 06250

R-464

Sunrise Northeast, Inc.

Inspection Date: Tuesday, August 26, 2008

DDS Region: North

Inspection Type: Standard

Inspection Report Citations Were Reported In The Following Regulatory Areas:

Regulatory Category

17a-227-11 Physical Requirements

11d Hazard prevention